

# Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



#### WORK ORDER INFORMATION

Work Order Name: WO/80008KN0699/1
Work Order Type: Weatherization

Audit Name: 80008KN0699-Audit

#### **CLIENT INFORMATION**

Client Name:

Address:

Client ID: 80008KN0699

Alt. Client ID: KNOX

### <u>AGENCY INFORMATION</u>

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 2000

Client Name:

Client ID: 80008KN0699 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0699/1 Report Run On: 5/6/2010 DOE Weatherization Assistant Version 8.6.0

Page 1 of 9

## Measures

	Measure 1 Floo	r/Ceiling Register			Component	s			Inspected
C	be seale Standard	gister to be replaced with d to existing duct boot. N ds for Weatherization Ma irs bedroom.	o change	s allov	ed. Refer to	Append	lix A-		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Floor/Ceiling Register	Each	1			] [.		
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
c	Other Detail								
			J	Measur	e Sub Total:			Sub Total:	-
	Field Notes:				,,				

	<i>Measure</i> 2 W	/indow Screen(QTY 4)W2,	N5,W3,N6	3	Componen	ts			Inspected
C	verify	to house diagram with wir measurements in the field ndix A- Standards for Weat a.	before ord	dering '	window scree	en(s). Re	efer to		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Window Screen	Each	4		· · · · · · · · · · · · · · · · · · ·			
2	Labor	Labor	Each	4		······································			
	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Fleld Notes:								

Work Order Name: WO/80008KN0699/1 Report Run On: 5/6/2010

Page 3 of 9

	Measure 3 Infilt	rotion Padata			Componen	4-			Inspected
Comment 4 DOOR WEATHERSTRIPS,,ATTIC ACSESS WEATHERTSTRIP,2  KNEEEWALL DOORS NEED WEATHERSTRIP.SEAL ALL PLUMBING PENETRATIONS.•Reduce air infiltration with 5 air seals. Each air seal is equal to 100 cfms. It is the responsibility of the contractor to find the air leaks. This is best performed with a Blower Door. Contractor must meet or exceed the targeted #. A house must not be brought below 1500 cfm @ 50 pascals. No CHANGE ORDER for air seals below the targeted #. "Open" Ring, Front Door, 3683 CFM @ 50 pascals. Target is 3183 CFM @ 50 PA									
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Infiltration Reduction	Each	5					
2	Labor	labor	Each	5		***************************************			
2	Other Detail								
			!	Measur	e Sub Total:		] 8	Sub Total:	
	Field Notes:							· · · · · · · · · · · · · · · · · · ·	

1	Measure 4 DWH	ł Pipe Insulation			Componen	ts			Inspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail								
				Measur	e Sub Total:		] .	Sub Total:	
	Field Notes:				***************************************			***************************************	

	Measure 5 DWH		Components					Inspected		
C	<b>comment</b> extend p	ressure relief pipe as ne	eded.							
				Estimated				Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Hot Water Equipm	DHW Tank Insulation	Each	1						
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.								
2	Labor	DHW Tank Insulation	Each	1						
O	Other Detail									
	Transition of the state of the									
				Measur	e Sub Total:		,	Sub Total:		
	Field Notes:			***************************************						
Measure 6 Door Deadbolt Lock (d1,d4)  Components  Comment Remove old dead bolt lock before installing new door lock. Door Lock must be 1st quality. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide. All keys given to home owner not anyone else. Changing due to double keyed cylinder.							Inspected			
		st Field Guide. All keys g	iven to ho	for W	/eatherizatio vner not anyo	n Materia				
	Changing	st Field Guide. All keys g g due to double keyed cy	iven to ho linder.	for W	eatherizatio vner not anyo Estimated	n Materia one else.	ls and	Actual		
	Changing  Material / Labor	st Field Guide. All keys g g due to double keyed cy Description / Comment	iven to ho linder. <i>Units</i>	for Wme ov	/eatherizatio vner not anyo	n Materia			Total	
	Changing	st Field Guide. All keys g g due to double keyed cy	iven to ho linder.	for W	eatherizatio vner not anyo Estimated	n Materia one else.	ls and	Actual		
1	Changing  Material / Labor	st Field Guide. All keys g g due to double keyed cy Description / Comment	iven to ho linder. <i>Units</i>	for Wme ov	eatherizatio vner not anyo Estimated	n Materia one else.	ls and	Actual		
1	Changing  Material / Labor  Unspecified	st Field Guide. All keys g g due to double keyed cy Description / Comment Door Deadbolt Lock (+)	iven to ho dinder. <i>Units</i> Each	for We own	eatherizatio vner not anyo Estimated	n Materia one else.	ls and	Actual		
1	Changing  Material / Labor  Unspecified  Labor	st Field Guide. All keys g g due to double keyed cy Description / Comment Door Deadbolt Lock (+)	iven to ho dinder. <i>Units</i> Each	for We own	eatherizatio vner not anyo Estimated	n Materia one else.	ls and	Actual		
1	Changing  Material / Labor  Unspecified  Labor	st Field Guide. All keys g g due to double keyed cy Description / Comment Door Deadbolt Lock (+)	iven to ho dinder. <i>Units</i> Each	for We own	eatherizatio vner not anyo Estimated	n Materia one else.	ls and	Actual		
1	Changing  Material / Labor  Unspecified  Labor	st Field Guide. All keys g g due to double keyed cy Description / Comment Door Deadbolt Lock (+)	iven to ho dinder.  Units Each Each	G for W me ov	eatherizatio vner not anyo Estimated	n Materia one else.	Qty	Actual		

Client Name:

Client ID: 80008KN0699 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0699/1 Report Run On: 5/6/2010 DOE Weatherization Assistant

Version 8.6.0 Page 6 of 9

	Measure 7 Doo	or Key Lock qty2 (d1,d4	)		Component	ts			Inspected
С	quality. Append	e old door lock before ins Must be thumb lever styl lix A- Standards for Weal All keys given to home o	e. No dout therization	ole key	ed cylinders.	. Refer t	o		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Unspecified	Door Key Lock (+)	Each	2					
2	Labor	labor	Each	2					
2	Other Detail								
L									
			1	Measur	e Sub Total:			Sub Total:	
	Fleld Notes:								

		mproper Venting of Bat aust Fan(QTY 3)	hroom		Component	ts			Inspected
C	<b>Comment</b> Bath Ver Attachm Guide.	nts installed to outside of ent A- Standards for Wea	home. No atherizatio	o chan on Mat	ges allowed. erials and Sc	Refer to outheast	Field		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Bath Vent w/ Piping to Outside	Each	3					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	3					
C	Other Detail								
						****			
				Measur	e Sub Total:			Sub Total:	
	Field Notes:	***************************************				*****			

	Measure	9 Repl	ace Double Cylinder De	adbolt L	ock	Componen	ts			Inspected
C	Comment	quality. I Appendi	old door lock before inst Must be thumb lever style x A- Standards for Weath Ill keys given to home ow	. No doul rerization	ble key Mater	ed cylinders ials and Sou	. Refer	to	ist	
						Estimated	,		Actual	
#	Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qt	y Unit Cos	t Total
1	Doors		Replace Double Cylinder Deadbolt Lock	Each	1	779.	. 12511			
			Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor		Labor	Each	1					
(	Other Detai	<i>I</i>								
Γ					F					
L	*****		*****			L	***************************************	_		
				i	Measur	e Sub Total:		_]	Sub Total:	
	Fleld Note	s:								
				Work Or	der Gra	nd Total:		Gra	and Total:	

Client ID: 80008KN0699 Alt. Client ID: KNOX DOE Weatherization Assistant Version 8.6.0

Report Run On: 5/6/2010